

AALIDHRA TEXCRAFT ENGINEERS

Mfr. and Labour Job undertaker of Textiles Machinery Parts & Accessories

Plot No. A-1/15 & 16, Gate No. 2, Hojiwala Ind. Estate, SUSML; Vanz, Sachin, 394 230, Surat, Gujarat.

Ref. No.

Date : 5/3/2015

DEAR SIR,

THIS IS INFORM YOU THAT YOU NEED TO REPLACE RAPIER LOOM OIL AFTER 1 – 2 MONTHS OF RUNNING WITH HIGH GRADE OIL MAKE SHELL OMALA S4 GX. GRADE. (ADVANCED SYNTHETIC INDUSTRIAL GEAR OIL)

HOW EVER, IF ABOVE SAID IS NOT TAKEN CARE, THERE MAY BE HEAVN MAINTANANCE OF BOTH END GEAR BOX WHICH IS NOT EASY. IT REPLACE AND ALSO MAY NOT BE FREE OF COST.

I HOPE YOU WILL TAKE ENOUGH CARE FOR TROUBLE FREE SERVICE LIFE OF YOUR RAPIER MACHINE.

THANKS & REGARDS.

